



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1105

Issue Date: 09/18/2026

Issue: Due to a supplier manufacturing issue, in some cases after powering up the radio, an “Error 8” message is shown on the front display.

BKR0122



Error 8:
Invalid Battery

Affected Models: BKR0122. (**Note:** Units with the SN lot code date between year 24, week 51 and year 26, week 13 [182B25002451xxxx and 182B25002613xxxx] might have the potential.)

Recommended Action: Only if this issue occurs, it is recommended to return units to BK Technologies for repair or replacement.

Please find the Factory Service Form at the following link: [form-pdf](#)

BK Technologies
Attn: Service Department
7100 Technology Drive
West Melbourne, FL. 32904

Importance: High