



# Product Announcement

## End of Service: KNG-P150 portable radio

### OVERVIEW

Effective 6/30/25, BK Technologies is no longer offering repair service on the following models of the KNG-P150 radio. See part number and description below.

Model Number	Description	Replacement
KNG-P150	136-174 MHz, 5000 channels, 6 Watt, P25 Digital/Analog Portable	BKR5000 or BKR9000
KNG-P150T2	136-174 MHz, 5000 channels, 6 Watt P25 Digital/Analog Portable without Keypad	BKR5000 or BKR9000
KNG-P150CMD	136-174 MHz, 5000 channels, 6 Watt, P25 Specialized Command Groups	BKR5000 or BKR9000

### EXISTING CUSTOMER CONTRACTS

All current contractual agreements will be honored.

### REPLACEMENT PRODUCTS

Please contact your BK sales representative to order. For more information, please visit <https://www.bktechnologies.com/>.

### CONTACT INFORMATION

Questions regarding the end of service on the above products should be directed to the Customer Service Dept. at 800-422-6281 or via email [service@bktechnologies.com](mailto:service@bktechnologies.com).

7100 Technology Drive  
West Melbourne, Florida 32904  
Phone: 321-984-1414  
Toll Free: 800-821-2900

[bktechnologies.com](https://www.bktechnologies.com)     